

General Environmental Incident Summary

Incident: 1780 **Notice:** 8/23/2012 0930 **Occurred:** 8/23/2012 0800
DEM Incident No: **No Further Action:** ☒
Responsible Party: Unknown
County: Burleigh
Twp Rng Sec Qtr: 139 80 30
Lat Long + Method: 46.83073 -100.82440 Derived from TRS
Location Description: Sheen check between Memorial and Railroad Bridges
Submitted By Info: Al Hunt
NDDoH Response Team
918 E Divide Ave
4th Floor
Bismarck ND 58501-1947
Received By Info:
Contact Info: Unknown
Bismarck ND
Affected Medium: 02 - water
Near. Occupied Bldg:
Type of Incident: Complaint
Release Contained:
Reported to NRC: Unknown
Contaminant: Unknown
Volume of Release:
Duration of Release:
Agriculture Related: No
EPA Extremely Hazardous Substance: Unknown
Number of Fatalities:
Number of Injuries:
Cause of Incident: Complaint of sheen on Missouri River
Risk Evaluation:
Potential Env. Impacts:
Action Taken/Planned:
Wastes Disposal Location:
Other Agencies Involved:

Updates

Date: 8/23/2012 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Notes:

Assigned to Al Hunt for investigation.

Updated Volume: None at the time of this update

Date: 8/23/2012 **Status:** Inspection

Author: Hunt, Al

Notes:

Walked western shoreline with Peter. No sheen was seen on the water. A little bio-sheen, but not gas or diesel. Peter contacted the report sender, explained it was bio-sheen. No photos taken.

Updated Volume: None at the time of this update